

## OAK GROVE ELEMENTARY, WEST COLUMBIA, SC



### **Project Description**

---

This project consisted of conducting OSF Chapter 1 and Chapter 17 inspections for the new kindergarten and multi-purpose room additions. Scope of work consisted of footing inspections, floor slabs, block fill mortar testing, structural steel inspections, roofing inspections, water proofing, fire proofing, HVAC, plumbing and electrical.

### **Project Cost**

---

\$2,500,000

### **Project Location**

---

West Columbia, South Carolina

### **Client Name and Contact**

---

MB Kahn

### **Scope of Services**

---

- OSF Inspections
- Chapter 1 Inspections
- Chapter 17 Inspections

## BLYTHEWOOD ACADEMY, BLYTHEWOOD, SC



### **Project Description**

---

This project consisted of conducting OSF Chapter 1 and Chapter 17 one story classroom addition. Scope of work consisted of footing inspections, floor slabs, block fill mortar testing, structural steel inspections, roofing inspections, water proofing, fire proofing, HVAC, plumbing and electrical.

### **Project Cost**

---

\$3,000,000

### **Project Location**

---

Blythewood, South Carolina

### **Client Name and Contact**

---

MB Kahn  
Jocelyn Boozer

### **Scope of Services**

---

- OSF Inspections
- Chapter 1 Inspections
- Chapter 17 Inspections

## SCDMH TUCKER ENERGY CENTER, COLUMBIA, SC



### **Project Description**

---

This project consisted of conducting OSF Chapter 17 inspections for a one story boiler room addition. Scope of work consisted of footing inspections, floor slabs, block fill mortar testing, structural steel inspections, roofing inspections, water proofing, fire proofing, HVAC, plumbing and electrical.

### **Project Cost**

---

\$1,500,000

### **Project Location**

---

Columbia, South Carolina

### **Client Name and Contact**

---

SCDMH  
Janice Timms

### **Scope of Services**

---

- OSF Inspections
- Chapter 17 Inspections

## PELION MIDDLE SCHOOL, PELION, SC



### **Project Description**

---

This project consisted of conducting OSF Chapter 1 and Chapter 17 inspections for a new two story classroom addition. Scope of work consisted of footing inspections, floor slabs, block fill mortar testing, structural steel inspections, roofing inspections, water proofing, fire proofing, HVAC, plumbing and electrical.

### **Project Cost**

---

\$4,000,000

### **Project Location**

---

Pelion, South Carolina

### **Client Name and Contact**

---

MB Kahn

### **Scope of Services**

---

- OSF Inspections
- Chapter 1 Inspections
- Chapter 17 Inspections